






Roof Leaking Assessment Report - Dataran

ROYAL SELANGOR CLUB


Location : Billiard Room



Location : Billiard Room



Location : Gym Male Toilet



Location : Gym



Location : Male Toilet



Location : DB Box Room



Location : Female Toilet

